



Air Quality Monitoring Report along the route alignment of MRT Line-6, September 2019

Serial	Package	Package Location	Independent Monitoring Group (IMG) Results ($\mu\text{g}/\text{m}^3$) (September 2019)	Air Quality Standards (ECR, 1997)
01.	CP-02	Depot Diabari Uttara	35.50 (Milestone College) and 32.35 (South part of Depot)	65 ($\mu\text{g}/\text{m}^3$)
02.	CP-03	Uttara 3 rd Phase to Pallabi	30.29 (Pallabi Station) and 12.95 (Bridge 8, Uttara 3 rd Phase)	
03.	CP-04	Pallabi to Agargaon	24.64 (Mirpur-10 Station)	
04.	CP-05	Agargaon to Karwanbazar	58.46 (Alrazi Hospital, Farmgate) and 45.39 (Khejurbagan)	
05.	CP-06	Karwanbazar to Motijheel	38.16 (Shahbag Station) and 24.22 (TSC)	

The result of Air Quality Monitoring Data of September 2019 along the route alignment of MRT Line-6 is below the Air Quality Standards (ECR, 1997). All mitigation measures are being done to keep the Air Quality along the route alignment of MRT Line-6 under control.


 26.11.2019
Krishna Kanta Biswas
 APD (EHSLAR)
 Dhaka Mass Rapid Transit
 Development Project (Line-6)
 Road Transport & Highways Division


 26.11.19
Md. Aftabuddin Talukder
 (Additional Secretary)
 Project Director
 Dhaka Mass Rapid Transit Development Project
 Ministry of Road Transport & Bridges